

MAKE			MODEL			GRADE		
Mitsubishi			OUTLANDER PHEV			G SAFETY PACKAGE		
YEAR	CC	FUEL	KMS	TRANS.	EXT. COLOR	INT. COLOR		
2014	2000	HV	44,354	<b>(AT)</b> MT	Pearl	Black		
MODEL CODE				CHASSIS NO.				
DLA-GG2W				GG2W-0105000				

## MECHANICAL, ELECTRICAL &amp; RUST


1	OIL LEAK	<b>(GOOD)</b>	FAIL		5	POWER MIRROR	<b>(GOOD)</b>	FAIL	NONE
2	ENGINE	<b>(GOOD)</b>	FAIL		6	POWER WINDOW	<b>(GOOD)</b>	FAIL	NONE
3	RUST UNDERNEATH	<b>(GOOD)</b>	FAIL		7	AIR CONDITIONER	<b>(GOOD)</b>	FAIL	NONE
4	RUST OTHERS	<b>(GOOD)</b>	FAIL		8	WARNING LAMP	<b>(GOOD)</b>	FAIL	

## INTERIOR

9	ROOF LINER	<b>(GOOD)</b>	FAIL	LOSE	RIP	
10	DOOR TRIM	<b>(GOOD)</b>	FAIL	LOSE	RIP	
11	DASH BOARD	<b>(GOOD)</b>	FAIL	CRACK	LIFTING	
12	SEATS	<b>(GOOD)</b>	FAIL	DIRT	RIP	CIGARETTE MARK
13	ROOM CONDITION	<b>(GOOD)</b>	FAIL	RIP	CIGARETTE SMELL	PET SMELL

## OPTIONS

AIRBAGS	<b>4</b>	KEY	<b>2</b>	AW SIZE	<b>18in.</b>	TAKATA AIRBAG	YES <b>(NO)</b>	RECALL DONE	
STABILITY CONTROL	<b>✓</b>	CRUISE CONTROL	<b>✓</b>	SUN ROOF		BACK CAMERA	<b>✓</b>	POWER SLIDING DOOR	L / R



(Remark)

 A (Scratch)  
Y (Crack)  
XX (Replacement)

 U (Dent)  
C (Corrode)

 d (Dimple)  
P (Paint Faded)  
X (Replacement requires)

 md (Many Dimples)  
W (Uneven paint)

S (Rust)