

MAKE			MODEL			GRADE		
Lexus			HS			HS250h Ver-I		
YEAR	CC	FUEL	KMS	TRANS.	EXT. COLOR	INT. COLOR		
2009	2400	HV	98,658	<b>AT</b> MT	Black	Brown		
MODEL CODE				CHASSIS NO.				
DAA-ANF10				ANF10-2012583				

## MECHANICAL, ELECTRICAL &amp; RUST



1	OIL LEAK	<b>GOOD</b>	FAIL		5	POWER MIRROR	<b>GOOD</b>	FAIL	NONE
2	ENGINE	<b>GOOD</b>	FAIL		6	POWER WINDOW	<b>GOOD</b>	FAIL	NONE
3	RUST UNDERNEATH	<b>GOOD</b>	FAIL		7	AIR CONDITIONER	<b>GOOD</b>	FAIL	NONE
4	RUST OTHERS	<b>GOOD</b>	FAIL		8	WARNING LAMP	<b>GOOD</b>	FAIL	

## INTERIOR

9	ROOF LINER	<b>GOOD</b>	FAIL	LOSE	RIP	
10	DOOR TRIM	<b>GOOD</b>	FAIL	LOSE	RIP	
11	DASH BOARD	<b>GOOD</b>	FAIL	CRACK	LIFTING	
12	SEATS	<b>GOOD</b>	FAIL	DIRT	RIP	CIGARETTE MARK
13	ROOM CONDITION	<b>GOOD</b>	FAIL	RIP	CIGARETTE SMELL	PET SMELL

## OPTIONS

AIRBAGS	<b>6</b>	KEY	<b>2</b>	AW SIZE	<b>18in.</b>	TAKATA AIRBAG	YES <b>NO</b>	RECALL DONE	
STABILITY CONTROL	<b>✓</b>	CRUISE CONTROL	<b>✓</b>	SUN ROOF		BACK CAMERA	<b>✓</b>	POWER SLIDING DOOR	L / R


 (Remark)  
 • CD,DVD

 A(Scratch)  
 Y(Crack)  
 XX(Replacement)

 U(Dent)  
 C(Corrode)

 d(Dimple)  
 P(Paint Faded)  
 X(Replacement requires)

 md(Many Dimples)  
 W(Uneven paint)

S(Rust)