


Car Number	Chassis Number
F00-B73	AZK10-2011373



(Remark)

Wheel cap missing

A(Scratch) U(Dent) S(Rust) W(Uneven paint) X(Crack) C(Corrode) P(Paint Faded)

XX(Replacement) X(Replacement requires) G(Stone chip in the glass) Scale: 1 < 2 < 3 < 4