


Car Number	Chassis Number
F06-C91	ANF10-2028685



(Remark)

**A**(Scratch)      **U**(Dent)      **S**(Rust)      **W**(Uneven paint)      **X**(Crack)      **C**(Corrode)      **P**(Paint Faded)  
**XX**(Replacement)      **X**(Replacement requires)      **G**(Stone chip in the glass)      **Scale: 1 < 2 < 3 < 4**