


Car Number	Chassis Number
F09-B23	ZVW50-6051855



(Remark)
 Left side mirror is broken

A(Scratch) **U**(Dent) **S**(Rust) **W**(Uneven paint) **X**(Crack) **C**(Corrode) **P**(Paint Faded)
XX(Replacement) **X**(Replacement requires) **G**(Stone chip in the glass) **Scale: 1 < 2 < 3 < 4**