


Car Number	Chassis Number
F21-C40	SXM10-7158670



(Remark)
 Both side power mirrors do not work automatically

A(Scratch) **U**(Dent) **S**(Rust) **W**(Uneven paint) **X**(Crack) **C**(Corrode) **P**(Paint Faded)
XX(Replacement) **X**(Replacement requires) **G**(Stone chip in the glass) **Scale: 1 < 2 < 3 < 4**