


Car Number

Chassis Number

F24-L80

ZVW41-3154902



(Remark)

Colour fade on steering wheel

A(Scratch)

U(Dent)

S(Rust)

W(Uneven paint)

X(Crack)

C(Corrode)

P(Paint Faded)

XX(Replacement)

X(Replacement requires)

G(Stone chip in the glass)

Scale: 1 < 2 < 3 < 4