


Car Number	Chassis Number
F26-C73	AYH30-0026125



(Remark)

A(Scratch) **U(Dent)** **S(Rust)** **W(Uneven paint)** **X(Crack)** **C(Corrode)** **P(Paint Faded)**
XX(Replacement) **X(Replacement requires)** **G(Stone chip in the glass)** **Scale: 1 < 2 < 3 < 4**