


Car Number	Chassis Number
G07-F69	ACA31-5049673



(Remark)

A (Scratch)	U (Dent)	S (Rust)	W (Uneven paint)	X (Crack)	C (Corrode)	P (Paint Faded)
XX (Replacement)	X (Replacement requires)		G (Stone chip in the glass)		Scale: 1 < 2 < 3 < 4	