


|            |                |
|------------|----------------|
| Car Number | Chassis Number |
| G10-F31    | NSP130-2188411 |



---

(Remark)

|                  |                          |          |                             |           |                      |                 |
|------------------|--------------------------|----------|-----------------------------|-----------|----------------------|-----------------|
| A (Scratch)      | U (Dent)                 | S (Rust) | W (Uneven paint)            | X (Crack) | C (Corrode)          | P (Paint Faded) |
| XX (Replacement) | X (Replacement requires) |          | G (Stone chip in the glass) |           | Scale: 1 < 2 < 3 < 4 |                 |