




DATE
2025/5/17

Car Number	Chassis Number
G18-D67	ANH20-8165004



(Remark)

A(Scratch)	U(Dent)	S(Rust)	W(Uneven paint)	X(Crack)	C(Corrode)	P(Paint Faded)
XX(Replacement)	X(Replacement requires)	G(Stone chip in the glass)	Scale: 1 < 2 < 3 < 4			